

Ethernet copper cable for IP67 switch - M12 connector - 3 m

TCSECL1M1M3S2

Discontinued on: Oct 9, 2023

① Discontinued

Product availability: Non-Stock - Not normally stocked in distribution facility

Main

Range of Product	ConneXium	
Accessory / separate part category	Connection accessories	
Accessory / Separate Part Type	Connecting cable	
Product or Component Type	Ethernet copper cable for IP67 switch	
Accessory / separate part destination	Ethernet box Ethernet switch	
Cable length	9.8 ft (3 m)	

Complementary

Range Compatibility	Modicon M340 automation platform Transparent Ready	
Electrical connection	2 male connectors, M12 straight 4 D coding	
Conductor material	Copper	

Environment

IP Degree of Protection IP67

Ordering and shipping details

Category	US1000T18407
Discount Schedule	000T
GTIN	3595863887532
Returnability	No
Country of origin	DE

Packing Units

Unit Type of Package 1	PCE
Number of Units in Package 1	1
Package 1 Height	1.97 in (5.0 cm)
Package 1 Width	7.87 in (20.0 cm)
Package 1 Length	7.87 in (20.0 cm)
Package 1 Weight	5.6 oz (158.0 g)
Unit Type of Package 2	S02

Price is "List Price" and may be subject to a trade discount – check with your local distributor or retailer for actual price.

Number of Units in Package 2	10
Package 2 Height	5.91 in (15.0 cm)
Package 2 Width	11.81 in (30.0 cm)
Package 2 Length	15.75 in (40.0 cm)
Package 2 Weight	4.184 lb(US) (1.898 kg)

Contractual warranty

Warranty 18 months



Schneider Electric aims to achieve Net Zero status by 2050 through supply chain partnerships, lower impact materials, and circularity via our ongoing "Use Better, Use Longer, Use Again" campaign to extend product lifetimes and recyclability.

How this information helps you >

Use Better

EU RoHS Directive	Pro-active compliance (Product out of EU RoHS legal scope)
China RoHS Regulation	China RoHS declaration
California proposition 65	WARNING: This product can expose you to chemicals including: Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov